Technical Service Bulletin #0908

New Burner Available On GU32 - 06/25/09

Grand Hall USA, Inc. 3838 West Miller Road

Garland, Texas 75041 TEL 866 946 1096 eterna

FAX 972 279 8440

Applicable Models:

501[11,12,21,22]1321 - GU32 501[11,12,21,22]1281 - GU28

Affected Serial #s:

Starting from G900453

Description:

The new upgraded Aluminum Fan Motor Assembly, P/N 302070299 is factory installed from G900453 onward (reference TSB#0907). This new Fan Motor Assembly uses a circular burner flange as opposed to the previously used rectangular burner flange. As such, the old burner assembly, P/N 301070088A, will NOT fit the new Fan Motor Assembly.

When ordering replacement burner assembly for units equipped with the new aluminum fan, please specify Aluminum Burner Assembly, and use P/N 301070302.



Consumer Notice: The information and instruction in this bulletin are intended for use by skilled professionals. These instructions should not be performed by consumers. Call your professional person for help.